



Figure 2 is a schematic diagram of a mechanical assembly 2. The assembly includes a shaft 2a, a pin 2b, a nut 2c, a washer 2d, a flange 2e, and a bearing 2f. The shaft 2a is shown with a flange 2e at one end and a bearing 2f at the other. The pin 2b passes through the shaft 2a and is secured by the nut 2c and washer 2d. The entire assembly is labeled 2.

Fig. 4A




Fig. 4B




Fig. 5A




Fig. 5B




Fig. 5C




Fig. 6A




Fig. 6B




Fig. 6C




Fig. 7A




Fig. 7B




Fig. 7C




Fig. 7D

